NORTH VIEW Housing Association

North View is a registered Scottish charity – charity registration number SC032963

ASBESTOS MANAGEMENT PLAN APPENDIX 5

Table 3

Total Score	Risk Priority	Recommendation
More than 17	Priority 1 (Highest Risk)	It is likely in a situation with such a high rating that individuals are currently being exposed to some level of asbestos fibre contamination. Situations falling within this category warrant urgent consideration. In most circumstances, immediate plans for the removal of the ACM concerned must be implemented, or as a minimum, the rapid sealing of the affected area.
13 to 16	Priority 2	Situations within this category still warrant urgent consideration, in that any slight deterioration in any one of a number of contributory factors must result in unacceptable deterioration within a short passage of time. In these situations, it is therefore necessary for the ACM to be removed on a programmed basis but usually within a year. In the meantime, emergency repair and sealing operations must be undertaken where any deterioration or damage occurs.
8 to 12	Priority 3	Situations within this category do not pose an imminent risk and likelihood of fibre release is low under existing conditions. It would be most appropriate within this category to monitor the situation, as deterioration must occur with the passage of time. It is recommended that situations within this category must be inspected on a sixmonthly basis to ascertain any change in circumstances which could require reassessment of priority rating into the priority 2 category. Consider removal if the item falls within a demolition or major refurbishment area and works is likely to disturb the material.
Less than 8	Priority 4 (Lowest Risk)	Situations within this category are low priority. The situation must be monitored on the basis of a one-year inspection cycle to ascertain any change to priority rating. Manage and consider removal if the item falls within a demolition or major refurbishment area and works is likely to disturb the material.